



## Introduction

Thank you for designing with the Zynq™ UltraScale+™ MPSoC family. Although AMD has made every effort to ensure the highest possible quality, the devices listed in [Table 1](#) are subject to the limitations described in the following errata.

### Devices

These errata apply to one or more of the devices shown in [Table 1](#). Refer to the **Device** column of [Table 2](#) for specific device applicability for each errata item.

*Table 1: Devices Affected by These Errata*

Product Family	Device	Speed Grade	Junction Temperature Range	IDCODE[31:0](1)	Package
Zynq UltraScale+ MPSoC	XCZU1CG	All	All	04688093	All
	XCZU2CG			14711093	
	XCZU3CG			14710093	
	XCZU3TCG			04718093	
	XCZU4CG			04721093	
	XCZU5CG			04720093	
	XCZU6CG			24739093	
	XCZU7CG			14730093	
	XCZU9CG			24738093	
	XCZU1EG	All	All	04688093	All
	XCZU2EG			14711093	
	XCZU3EG			14710093	
	XCZU3TEG			04718093	
	XCZU4EG			04721093	
	XCZU5EG			04720093	
	XCZU6EG			24739093	
	XCZU7EG			14730093	
	XCZU9EG			24738093	
	XCZU11EG			04740093	
	XCZU15EG	14750093			
	XCZU17EG	14759093			
	XCZU19EG	14758093			
	XCZU4EV	All	All	04721093	All
	XCZU5EV			04720093	
	XCZU7EV			14730093	

AMD Adaptive Computing is creating an environment where employees, customers, and partners feel welcome and included. To that end, we’re removing noninclusive language from our products and related collateral. We’ve launched an internal initiative to remove language that could exclude people or reinforce historical biases, including terms embedded in our software and IPs. You may still find examples of non-inclusive language in our older products as we work to make these changes and align with evolving industry standards. Follow this [link](#) for more information.

Table 1: Devices Affected by These Errata (Cont'd)

Product Family	Device	Speed Grade	Junction Temperature Range	IDCODE[31:0] <sup>(1)</sup>	Package
XA Zynq UltraScale+ MPSoC	XAZU1EG	All	All	04688093	All
	XAZU2EG			14711093	
	XAZU3EG			14710093	
	XAZU3TEG			04718093	
	XAZU11EG			04740093	
	XAZU4EV			04721093	
	XAZU5EV			04720093	
	XAZU7EV			14730093	
XQ Zynq UltraScale+ MPSoC	XQZU3EG	All	All	14710093	All
	XQZU5EV			04720093	
	XQZU7EV			14730093	
	XQZU9EG			24738093	
	XQZU11EG			04740093	
	XQZU15EG			14750093	
	XQZU19EG			14758093	

**Notes:**

1. The most-significant hexadecimal digit (IDCODE[31:28]) is a revision field. These errata affect devices with the shown revision, or later.

## Links to Detailed Errata Descriptions

This section provides links to detailed descriptions of each issue known at the release time of this document. Additional information, including any work-arounds, is available in the associated answer record linked from each errata description. A list of software tools that implement errata work-arounds is found in [Answer Record 68750](#).

In the summary tables, the Topic and Errata Issue items listed in the “Errata Issue” column are clickable links to the more detailed information in the body of the document. Topics are listed in *alphabetical order*, while errata issues, *within each topic*, are listed in *reverse chronological order* (i.e., new issues listed first). New, updated, or newly closed errata issues appear in ***blue, bold, italic*** type; existing errata or previously closed errata issues appear in regular ***blue*** type.

Table 2: Summary Table of Processing System Issues

Errata Issue	Device	Answer Record <sup>(1)</sup>	Status
<b>Processing System (PS) Errata</b>			
<b>Application Processing Unit</b>			
<a href="#">Speculative AT Instruction Using Out-Of-Context Translation Regime Could Cause Subsequent Request To Generate An Incorrect Translation</a>	All	76211	Will Not Fix
<a href="#">PMU Counter Values Might Be Inaccurate When Monitoring Certain Events</a>	All	68878	Will Not Fix
<a href="#">An Eviction Might Overtake A Cache Clean Operation</a>	All	68874	Will Not Fix
<a href="#">A Store-Exclusive Instruction Might Pass When It Should Fail</a>	All	68875	Will Not Fix
<a href="#">Loads Of Mismatched Size Might Not Be Single-Copy Atomic</a>	All	68876	Will Not Fix
<a href="#">Reads Of PMEVCNTR&lt;n&gt; Are Not Masked By HDCR.HPMN</a>	All	68877	Will Not Fix
<a href="#">AArch64 Unconditional Branch Might Jump To Incorrect Address</a>	All	68880	Will Not Fix
<a href="#">Direct Branch Instructions Executed Before A Trace Flush Might Be Output In An Atom Packet After Flush Acknowledgment</a>	All	68882	Will Not Fix
<a href="#">APB Data Is Not Masked When PSLVERR Is Set</a>	All	68946	Will Not Fix
<a href="#">Incorrect Prefetch In V7S Mode</a>	All	66115	Will Not Fix
<a href="#">Updating A Translation Entry To Change Page Size Might Cause Data Corruption</a>	All	66116	Will Not Fix
<a href="#">Instruction Sequences Containing AES Instructions Might Produce Incorrect Results</a>	All	65853	Will Not Fix
<a href="#">Load Might Read Incorrect Data</a>	All	65854	Will Not Fix
<a href="#">Memory Locations Might Be Accessed Speculatively Due To Instruction Fetches When HCR.VM Is Set</a>	All	65855	Will Not Fix
<a href="#">Non-Allocating Reads Might Prevent A Store Exclusive From Passing</a>	All	65857	Will Not Fix
<a href="#">Write Of JMCR In EL0 Does Not Generate An UNDEFINED Exception</a>	All	65858	Will Not Fix

Table 2: Summary Table of Processing System Issues (Cont'd)

Errata Issue	Device	Answer Record <sup>(1)</sup>	Status
<b>Boot and Configuration</b>			
Primary Boot Is Not Supported With eMMC Devices That Require CMD6 Busy Time Greater Than 1 ms	All	000034596	Will Not Fix
Boot From NAND Might Fail If There Is Data Corruption In The First Parameter Page	All	68615	Will Not Fix
<b>CAN Controller</b>			
CAN Controller Does Not Send A Single Remote Transmission Request	All	000035301	Will Not Fix
<b>Controller for PCI Express</b>			
Sending Modified Compliance Pattern Requires Additional PCIe Register Programming	All	68534	Will Not Fix
PCIe DMA Status Update Might Happen After Interrupt Is Generated	All	68535	Will Not Fix
Under Heavy Read Traffic Conditions, The AXI-PCIe Bridge Arbitration Algorithm Might Incorrectly Select A Winning Requestor	All	68536	Will Not Fix
AXI-PCIe Bridge Does Not Drop MemWr TLP With ECRC Errors	All	68537	Will Not Fix
PCIe Generates Two Fatal Errors For Poisoned CfgWr TLPs	All	68539	Will Not Fix
PCIe Logs Incorrect Header In AER Register	All	68540	Will Not Fix
Controller For PCI Express Might Not Exit From Loopback Mode	All	68541	Will Not Fix
PCIe DMA Completion Error Status Bit From Aborted DMA Transfers Might Persist Through DMA Channel Reset	All	68542	Will Not Fix
<b>DDR Memory Controller</b>			
DDR Memory Controller Minimum Data Rate Is 1,000Mb/s	I, Q, M Temperature Grade Devices	71707	Will Not Fix
LPDDR3/LPDDR4 Temperature Derating Does Not Work When Initial DRAM Temperature Is Greater Than 85°C	All	70769	Will Not Fix
DDR Memory Controller Does Not Meet tSTAB Requirement For DDR3/DDR4 RDIMMs	All	68543	Will Not Fix
Accessing Unimplemented Registers In DDR Controller Causes Slave Error	All	65865	Will Not Fix
<b>Gigabit Ethernet Controller</b>			
Incorrect Transmission Of Pause Frames In Response To Reception Of Pause Frames With Unicast Or Known Multicast Address	All	68546	Will Not Fix
<b>Graphics Processing Unit (GPU)</b>			
Pixel Processor Write Boundary High Address Value Is Constant	EG Devices	69051	Will Not Fix
DMA Controller Always Marks Transactions As Secure	EG Devices	69052	Will Not Fix

Table 2: Summary Table of Processing System Issues (Cont'd)

Errata Issue	Device	Answer Record <sup>(1)</sup>	Status
<b>I2C</b>			
Dynamically Changing Controller Mode To Master From A Previous Slave Mode Might Cause Unnecessary Transfer On The I2C Bus	All	65869	Will Not Fix
<b>PS-GTR</b>			
Multi-lane Link Alignment Of PCIe Might Require Greater Than One SKP Ordered Set	All	65875	Will Not Fix
PS-GTR Ignores PCIe SKP Ordered Set With Odd Boundary Alignment	All	68547	Will Not Fix
<b>Real-Time Processing Unit (RPU)</b>			
Self-Modify Code In Non-Cacheable Memory Might Not Work With A Slow Memory System	All	68548	Will Not Fix
Processor Might Deadlock Or Lose Data When Configured With Cache-ECC	All	65878	Will Not Fix
Watchpoint Access In A Store Multiple Is Not Masked	All	65879	Will Not Fix
<b>SATA Controller</b>			
Switching From Slumber Or Partial Sleep To The Active State Does Not Always Work Properly	All	68971	Will Not Fix
Incorrect Indication Of Overflow As CRC Error	All	65880	Will Not Fix
Incorrect SRST Completion Indication To SATA Host Software	All	65881	Will Not Fix
SATA Device Sleep State Is Not Supported In The Controller	All	65882	Will Not Fix
<b>SD/SDIO/eMMC Controller</b>			
In An Asynchronous Multiprocessing Environment, The SD/SDIO Tap Delays Might Get Asynchronously Updated, Resulting In Incorrect Configuration Of Tap Delay Settings	All	68549	Will Not Fix
Default Value Of SDIO Auto-Tuning Refresh Register Is Incorrect	All	68550	Will Not Fix
SD Auto-Tuning Requires Received Data Buffer To Be Emptied By Software	All	68551	Will Not Fix
Switching From 64-Bit DMA Mode To 32-Bit DMA Mode Might Cause Incomplete Data Transfer	All	65883	Will Not Fix
<b>Security</b>			
PS DNA Is Not Write Protected And Is Different Than PL DNA	All	71342	Will Not Fix
<b>SPI Controller</b>			
SPI Controller Might Not Update RX_NEMPTY Flag, Showing Incorrect Status Of The Receive FIFO	All	65885	Will Not Fix
<b>System Test and Debug</b>			
PS DDR Inputs Do Not Switch To Boundary-Scan Compatible Mode	All	69180	Will Not Fix
ETM Might Assert AFREADY Before All Data Has Been Output	All	68879	Will Not Fix
ETM Might Lose Counter Events While Entering wfx Mode	All	68883	Will Not Fix

Table 2: Summary Table of Processing System Issues (Cont'd)

Errata Issue	Device	Answer Record <sup>(1)</sup>	Status
<a href="#">ETM Might Trace An Incorrect Exception Address</a>	All	68884	Will Not Fix
<a href="#">APB Access To ETM Space While Core Is In Retention Will Never Complete</a>	All	68885	Will Not Fix
<a href="#">ETM Does Not Report IDLE State When Disabled And Using OS Lock</a>	All	68886	Will Not Fix
<a href="#">ATB Asynchronous Bridge Breaks Discovery In Integration Mode</a>	All	65887	Will Not Fix
<a href="#">TPIU Fails To Output Sync After The Pattern Generator Is Disabled In Normal Mode</a>	All	65889	Will Not Fix
<a href="#">Reset State Of ATB Flush Acknowledge Is Incorrect</a>	All	65890	Will Not Fix
<a href="#">Timestamp Replicator Might Stall Synchronization</a>	All	65892	Will Not Fix
<b>USB 2.0/3.0 Host and Device, and USB 2.0 OTG Controller</b>			
<a href="#">System Might Hang During Suspend/Resume Stages</a>	All	67667	Will Not Fix
<a href="#">The tPortConfiguration Timer Resets During Recovery, Violating USB 3.0 Specification</a>	All	68553	Will Not Fix
<a href="#">USB 2.0 Host Controller Does Not Assert Port Reset In Resume State</a>	All	68554	Will Not Fix
<a href="#">Incorrect Assertion Of Hot Reset Might Occur In USB 3.0 Host Mode</a>	All	68555	Will Not Fix
<a href="#">Request For U3 Transition Might Get Dropped When The USB 3.0 Host Controller Transitions From U1 To U2 State</a>	All	68556	Will Not Fix
<a href="#">USB Full-Speed Device Does Not Enter Hibernation State During Disconnect</a>	All	68557	Will Not Fix

**Notes:**

1. A list of software tools that implement errata work-arounds is found in [Answer Record 68750](#).

Table 3: Summary Table of Programmable Logic Issues

Errata Issue	Device	Answer Record	Status
<b>Programmable Logic (PL) Errata</b>			
<b>Video Codec Unit</b>			
<a href="#">Decoding An HEVC Video Bitstream With Level 4 Or 4.1 With Greater Than 4K Pixels Per Line Results In Corruption In The Decoded Picture</a>	EV Devices	69340	Will Not Fix
<a href="#">Decoding An HEVC Video Bitstream With 8K Pixels Per Line With Sample Adaptive Offset (SAO) Filter Enabled Results In Corruption In The Decoded Picture</a>	EV Devices	69341	Will Not Fix
<a href="#">Decoding An 8K CAVLC Video Bitstream Might Hang</a>	EV Devices	69053	Will Not Fix

## Processing System (PS) Errata Detailed Descriptions

### Application Processing Unit

#### ***Speculative AT Instruction Using Out-Of-Context Translation Regime Could Cause Subsequent Request To Generate An Incorrect Translation***

[Answer 76211](#)

A speculative Address Translation (AT) instruction translates using registers that are associated with an out-of-context translation regime and caches the resulting translation in the TLB. A subsequent translation request that is generated when the out-of-context translation regime is current uses the previous cached TLB entry, producing an incorrect virtual to physical mapping.

This is a third-party errata (Arm, Inc. 1530924); this issue will not be fixed.

#### ***PMU Counter Values Might Be Inaccurate When Monitoring Certain Events***

[Answer 68878](#)

The performance monitor counters might be inaccurate when detecting some types of events.

This is a third-party errata (Arm, Inc. 855827); this issue will not be fixed.

#### ***An Eviction Might Overtake A Cache Clean Operation***

[Answer 68874](#)

The memory store transaction order for simultaneous cache line eviction trigger and cache clean operation might be stored to memory in the wrong order.

This is a third-party errata (Arm, Inc. 855873); this issue will not be fixed.

#### ***A Store-Exclusive Instruction Might Pass When It Should Fail***

[Answer 68875](#)

A Load-Exclusive instruction to cacheable memory might set the monitor to the exclusive state when the processor does not have exclusive access to the line. A subsequent Store-Exclusive instruction might pass when it should fail.

This is a third-party errata (Arm, Inc. 855872); this issue will not be fixed.

#### ***Loads Of Mismatched Size Might Not Be Single-Copy Atomic***

[Answer 68876](#)

In some unusual code sequences, the CPU might not meet the requirements of a single-copy atomic load.

This is a third-party errata (Arm, Inc. 855830); this issue will not be fixed.

***Reads Of PMEVCNTR<n> Are Not Masked By HDCR.HPMN***[Answer 68877](#)

EL2 software might not always restrict access to the performance counters by non-secure EL0 and EL1 software to a subset of the counters.

This is a third-party errata (Arm, Inc. 855829); this issue will not be fixed.

***AArch64 Unconditional Branch Might Jump To Incorrect Address***[Answer 68880](#)

When executing in AArch64 state with address translation disabled and under certain conditions, an unconditional immediate branch instruction to a single specific address might jump to an incorrect address.

This is a third-party errata (Arm, Inc. 852521); this issue will not be fixed.

***Direct Branch Instructions Executed Before A Trace Flush Might Be Output In An Atom Packet After Flush Acknowledgment***[Answer 68882](#)

When trace is enabled, the processor attempts to combine multiple direct branch instructions into a single atom packet. If an atom packet is in the process of being generated, the processor does not force completion of the packet prior to acknowledging the flush request.

This is a third-party errata (Arm, Inc. 852071); this issue will not be fixed.

***APB Data Is Not Masked When PSLVERR Is Set***[Answer 68946](#)

When the APB access to the performance monitor, breakpoint, or watchpoint registers is disabled, the register value is erroneously included with the APB response.

This is a third-party errata (Arm, Inc. 855874); this issue will not be fixed.

***Incorrect Prefetch In V7S Mode***[Answer 66115](#)

Under certain conditions, the Cortex-A53 MPCore memory management unit (MMU) might incorrectly prefetch a single descriptor past the 1KB boundary of the L2 table, resulting in a prefetch abort.

This is a third-party errata (Arm, Inc. 826419); this issue will not be fixed.

***Updating A Translation Entry To Change Page Size Might Cause Data Corruption***[Answer 66116](#)

When the MMU prefetches a translation table entry and the page size of the prefetched translation table entry has changed, then the MMU updates the cache with incorrect translation table attributes that do not correspond to the old or the new entry.

This is a third-party errata (Arm, Inc. 841119); this issue will not be fixed.

***Instruction Sequences Containing AES Instructions Might Produce Incorrect Results***[Answer 65853](#)

Certain sequences of instructions that include AES instructions might cause incorrect results to be generated when executed in AArch64 state on the Cortex-A53 processor.

This is a third-party errata (Arm, Inc. 845819); this issue will not be fixed.

***Load Might Read Incorrect Data***[Answer 65854](#)

When executing in AArch32 state at EL0, a load instruction to the same offset within a different 4GB region as a recent previous load in AArch64 state might read incorrect data.

This is a third-party errata (Arm, Inc. 845719); this issue will not be fixed.

***Memory Locations Might Be Accessed Speculatively Due To Instruction Fetches When HCR.VM Is Set***[Answer 65855](#)

The Armv8 architecture requires that when all associated stages of translation are disabled for the current exception level, memory locations are only accessed due to instruction fetches within the same or next translation granule while an instruction that has been or will be fetched due to sequential execution.

This is a third-party errata (Arm, Inc. 843819); this issue will not be fixed.

***Non-Allocating Reads Might Prevent A Store Exclusive From Passing***[Answer 65857](#)

If an Arm Cortex-A53 processor is executing a load and store exclusive instruction in a loop, certain allowed conditions might cause the store exclusive instruction to repeatedly fail. This includes another processor repeatedly writing to the same cache line. In addition, a non-allocating load from another processor might also cause the store exclusive instruction to repeatedly fail.

This is a third-party errata (Arm, Inc. 836870); this issue will not be fixed.

***Write Of JMCR In EL0 Does Not Generate An UNDEFINED Exception***[Answer 65858](#)

When EL0 is using AArch32 register width state and a write is performed in EL0 to JMCR, the write is permitted but ignored. The intended behavior is that the instruction should be UNDEFINED.

This is a third-party errata (Arm, Inc. 836919); this issue will not be fixed.

**Boot and Configuration*****Primary Boot Is Not Supported With eMMC Devices That Require CMD6 Busy Time Greater Than 1 ms***[Answer 000034596](#)

The boot ROM does not support primary boot from eMMC devices requiring CMD6 R1b busy time greater than 1 ms.

This issue will not be fixed.

***Boot From NAND Might Fail If There Is Data Corruption In The First Parameter Page***[Answer 68615](#)

When NAND is used as the primary boot device and there is data or CRC corruption in the first parameter page, the CSU Boot ROM (CBR) might fail to boot from the NAND device.

This issue will not be fixed.

**CAN Controller*****CAN Controller Does Not Send A Single Remote Transmission Request***[Answer 000035301](#)

The CAN Controller does not send a single remote transmission request (RTR).

This issue will not be fixed.

**Controller for PCI Express*****Sending Modified Compliance Pattern Requires Additional PCIe Register Programming***[Answer 68534](#)

The controller for PCIe is capable of sending both a compliance pattern and a modified compliance pattern. Transmission of a modified compliance pattern requires programming of Device Control Register 2, Enter Modified Compliance bit set to 1.

This issue will not be fixed.

***PCIe DMA Status Update Might Happen After Interrupt Is Generated***[Answer 68535](#)

The PCIe DMA controller's data transfer completion status might get updated after a completion interrupt is generated when the destination for the interrupt is configured as PCIe.

This issue will not be fixed.

***Under Heavy Read Traffic Conditions, The AXI-PCIe Bridge Arbitration Algorithm Might Incorrectly Select A Winning Requestor***[Answer 68536](#)

Under heavy read traffic conditions, the AXI-PCIe bridge might incorrectly select a winning port requesting arbitration, resulting in additional delay for completion of read requests from specific sources.

This issue will not be fixed.

***AXI-PCIe Bridge Does Not Drop MemWr TLP With ECRC Errors***[Answer 68537](#)

The AXI-PCIe bridge does not drop MemWr TLPs with ECRC errors. The host software must check Advanced Error Reporting (AER) registers and determine if there are errors in the packet. An interrupt can be generated to indicate the condition in software.

This issue will not be fixed.

***PCIe Generates Two Fatal Errors For Poisoned CfgWr TLPs***[Answer 68539](#)

When configured as an Endpoint, the controller for PCIe transmits two fatal error message packets to the link partner for poisoned CfgWr requests, instead of one.

This issue will not be fixed.

***PCIe Logs Incorrect Header In AER Register***[Answer 68540](#)

When advanced error reporting (AER) is enabled and the controller for PCIe receives an unexpected completion packet, it logs the AER header register incorrectly with all 1s.

This issue will not be fixed.

**Controller For PCI Express Might Not Exit From Loopback Mode**[Answer 68541](#)

When loopback is enabled in PCIe Gen2 mode and a rate change is requested by the link partner followed by a loopback exit request, the controller might not exit loopback mode if Electrical Idle Ordered Sets (EIOSs) are dropped at the receiver.

This issue will not be fixed.

**PCIe DMA Completion Error Status Bit From Aborted DMA Transfers Might Persist Through DMA Channel Reset**[Answer 68542](#)

When a PCIe DMA transfer is aborted and the PCIe DMA channel is unable to finish the DMA transfer, the DMA completion register error status bit persists after a DMA reset is issued.

This issue will not be fixed.

**DDR Memory Controller****DDR Memory Controller Minimum Data Rate Is 1,000Mb/s**[Answer 71707](#)

The PS DDR memory controller minimum data rate is 1,000Mb/s for industrial (I), automotive (Q), and military (M) temperature grade devices. Extended (E) temperature grade devices are not affected.

This issue will not be fixed.

**LPDDR3/LPDDR4 Temperature Derating Does Not Work When Initial DRAM Temperature Is Greater Than 85°C**[Answer 70769](#)

The PS DDR memory controller defaults to an initial nominal 1x refresh rate (1x tREFI), and only updates the refresh rate when the temperature update flag (TUF) from MR4[7] is 1.

If the LPDDR3/LPDDR4 memory starts above 85°C, the TUF will not be asserted. Thus, the controller will not adjust the DRAM refresh rate and the associated temperature derating AC timing parameters.

This issue will not be fixed.

**DDR Memory Controller Does Not Meet tSTAB Requirement For DDR3/DDR4 RDIMMs**[Answer 68543](#)

When the PS DDR3/DDR4 clock is enabled after exiting from a power-save mode, the stabilization time tSTAB for DDR3/DDR4 RDIMM is not guaranteed, which causes a violation of the registering clock driver specification.

This issue will not be fixed.

## ***Accessing Unimplemented Registers In DDR Controller Causes Slave Error***

[Answer 65865](#)

When an unimplemented register in the PS DDR controller is accessed by a read or write operation, a slave error is incorrectly returned.

This issue will not be fixed.

## **Gigabit Ethernet Controller**

### ***Incorrect Transmission Of Pause Frames In Response To Reception Of Pause Frames With Unicast Or Known Multicast Address***

[Answer 68546](#)

When the Gigabit Ethernet controller receives pause frames with a destination address not set to a known multicast address or unicast address, the controller does not inhibit transmission and transmits pause frames incorrectly, leading to compliance failure.

This issue will not be fixed.

## **Graphics Processing Unit (GPU)**

### ***Pixel Processor Write Boundary High Address Value Is Constant***

[Answer 69051](#)

The GPU WRITE\_BOUNDARY\_HIGH register is reserved and the GPU always uses a High value of FFFF\_FF00h for bounded writes.

This is a third-party errata (Arm, Inc. 578786). This issue will not be fixed.

### ***DMA Controller Always Marks Transactions As Secure***

[Answer 69052](#)

The GPU DMA controller always drives AxPROT[1] Low during a transaction, indicating it is secure. This can allow access to secure areas. The XMPU, XPPU, and SMMU can be used to mitigate this behavior.

This issue will not be fixed.

## I2C

### ***Dynamically Changing Controller Mode To Master From A Previous Slave Mode Might Cause Unnecessary Transfer On The I2C Bus***

[Answer 65869](#)

When the I2C controller's mode is dynamically changed from slave to master after a slave address is written, an unwanted start condition might be generated, causing unnecessary transfers on the bus.

This issue will not be fixed.

## PS-GTR

### ***Multi-lane Link Alignment Of PCIe Might Require Greater Than One SKP Ordered Set***

[Answer 65875](#)

The PS-GTR block might repeat or drop two bytes of data during multi-lane link alignment, causing data corruption in the controller for PCIe. The corruption continues until the next SKP ordered set (OS) is received. PCIe protocol is capable of handling such errors by re-transmitting the packets that have not been received by the connected device. No work-around is necessary. There is no impact on PCIe performance.

This issue will not be fixed.

### ***PS-GTR Ignores PCIe SKP Ordered Set With Odd Boundary Alignment***

[Answer 68547](#)

The deskew block in the PS-GTR block ignores the PCIe SKP ordered set (OS) that is aligned to an odd word boundary. It performs lane-to-lane deskew based on an even word boundary.

This issue will not be fixed.

## Real-Time Processing Unit (RPU)

### ***Self-Modify Code In Non-Cacheable Memory Might Not Work With A Slow Memory System***

[Answer 68548](#)

The Cortex-R5 processor might execute an old instruction or a corrupted instruction when a program executing on the processor writes to a non-cacheable memory location that is subsequently used to execute an instruction.

This is a third-party errata (Arm, Inc. 853474). This issue will not be fixed.

***Processor Might Deadlock Or Lose Data When Configured With Cache-ECC***[Answer 65878](#)

In a very rare scenario, when the Cortex-R5 processor accesses the cache memory with ECC enabled, resulting in an L1 data cache miss, the store buffer present in the Cortex-R5 processor might enter into a state that prevents any write transactions to proceed to the L1 cache memory or L2 memory system, causing prevention of instruction execution or write data loss scenarios.

This is a third-party errata (Arm, Inc. 780125); this issue will not be fixed.

***Watchpoint Access In A Store Multiple Is Not Masked***[Answer 65879](#)

The Arm Cortex-R5F processor implements synchronous watchpoints. A synchronous watchpoint generated during a store multiple instruction must ensure that the watchpointed access does not perform writes on the bus to update memory. This requirement is not met, and the processor incorrectly updates memory for a watchpointed access.

This is a third-party errata (Arm, Inc. 756523); this issue will not be fixed.

**SATA Controller*****Switching From Slumber Or Partial Sleep To The Active State Does Not Always Work Properly***[Answer 68971](#)

Wakeup occurs from slumber or partial sleep using the PxCMD [ICC] interface communication control bits, but the controller does not signal the PxIS [DHRS] interrupt response bit, causing the interrupt handler to hang. When using the DMA trigger wakeup bit in the PxCI register, the controller does not initiate an H2D FIS command to the device, causing software to time out and re-enumerate the device.

This issue will not be fixed.

***Incorrect Indication Of Overflow As CRC Error***[Answer 65880](#)

The SATA controller reports a CRC error instead of an overflow error in the PxSERR register when there is an overflow condition.

This issue will not be fixed.

***Incorrect SRST Completion Indication To SATA Host Software***[Answer 65881](#)

When the SATA host controller software sends SRST OFF FIS to the device, the controller does not set the BSY bit, which incorrectly communicates completion of the SRST FIS command to the host software.

This issue will not be fixed.

***SATA Device Sleep State Is Not Supported In The Controller***[Answer 65882](#)

The SATA controller does not support device sleep state.

This issue will not be fixed.

**Security*****PS DNA Is Not Write Protected And Is Different Than PL DNA***[Answer 71342](#)

The PS DNA value, which is read via PS APB addresses `0xFFCC100C`, `0xFFCC1010`, and `0xFFCC1014`, or read via the SDK `XiLSKey_ZynqMp_EfusePs_ReadDna` API, is not protected against change from intentional writes. Use the PL DNA for applications requiring an unchangeable, unique device identifier. The PS DNA value is different than the PL DNA value, which is used with 2D barcode device lookup.

This issue will not be fixed.

## SD/SDIO/eMMC Controller

### ***In An Asynchronous Multiprocessing Environment, The SD/SDIO Tap Delays Might Get Asynchronously Updated, Resulting In Incorrect Configuration Of Tap Delay Settings***

[Answer 68549](#)

The SD/SDIO controllers share a common register (with different bit fields) for configuring the tap delay values. In an asynchronous multiprocessing environment, when each processor updates the tap delay settings asynchronously, it is possible that the tap delay settings are not properly updated when the following conditions occur:

1. Processor 0 reads tap delay register for SD/SDIO controller instance 0
2. Processor 1 reads tap delay register for SD/SDIO controller instance 1 (which is the same as instance 0)
3. Processor 1 writes tap delay register for SD/SDIO controller instance 1 (which is the same as instance 0)
4. Processor 0 over-writes (based on step 1) tap delay register for SD/SDIO controller instance 1 (which is the same as instance 0)

Software needs to ensure that only one processor updates the tap delay configurations.

This issue will not be fixed.

### ***Default Value Of SDIO Auto-Tuning Refresh Register Is Incorrect***

[Answer 68550](#)

The default value of the auto-tuning refresh register is incorrect and indicates auto-tuning needs to be triggered periodically by the SDIO software.

This issue will not be fixed.

### ***SD Auto-Tuning Requires Received Data Buffer To Be Emptied By Software***

[Answer 68551](#)

During the auto-tuning process, the SD host controller fills the received buffer with training data, which needs to be emptied by host software after auto-tuning is completed.

This issue will not be fixed.

### ***Switching From 64-Bit DMA Mode To 32-Bit DMA Mode Might Cause Incomplete Data Transfer***

[Answer 65883](#)

When the DMA transfer mode is dynamically changed from 64-bit mode to 32-bit mode in the SD/SDIO controller, the DMA fails to complete the data transfer and generates an error response.

This issue will not be fixed.

## SPI Controller

### ***SPI Controller Might Not Update RX\_NEMPTY Flag, Showing Incorrect Status Of The Receive FIFO***

[Answer 65885](#)

The RX\_NEMPTY flag in the SPI Controller is not updated for every change in the received FIFO's threshold value. The flag might show an incorrect value and might not reflect the RX FIFO non-empty status.

This issue will not be fixed.

## System Test and Debug

### ***PS DDR Inputs Do Not Switch To Boundary-Scan Compatible Mode***

[Answer 69180](#)

The PS DDR inputs do not switch to a boundary-scan compatible mode during the JTAG EXTEST, EXTEST\_PULSE, or EXTEST\_TRAIN operations and can fail to capture valid input High signal values.

This issue will not be fixed.

### ***ETM Might Assert AFREADY Before All Data Has Been Output***

[Answer 68879](#)

The ready signal from the AMBA Trace Bus (ATB) might assert before the entire trace is output.

This is a third-party errata (Arm, Inc. 853172); this issue will not be fixed.

### ***ETM Might Lose Counter Events While Entering wfx Mode***

[Answer 68883](#)

If the ETM resources become inactive because of low-power state, there is a one-cycle window during which the counters and the sequencer might ignore counter-at-zero resources.

This is a third-party errata (Arm, Inc. 851871); this issue will not be fixed.

### ***ETM Might Trace An Incorrect Exception Address***

[Answer 68884](#)

Under certain conditions, the address in an exception packet might be incorrectly set to the target address of the exception. The trace stream is not corrupted.

This is a third-party errata (Arm, Inc. 851672); this issue will not be fixed.

***APB Access To ETM Space While Core Is In Retention Will Never Complete***[Answer 68885](#)

When a core is in retention mode, an APB request to the ETM causes the core to exit retention, but not drive PREADYDBG HIGH, and the APB transaction hangs.

This is a third-party errata (Arm, Inc. 853175); this issue will not be fixed.

***ETM Does Not Report IDLE State When Disabled And Using OS Lock***[Answer 68886](#)

When the OS Lock feature is used by software to disable the debug access, the ETM does not indicate when it is safe to power down.

This is a third-party errata (Arm, Inc. 855871); this issue will not be fixed.

***ATB Asynchronous Bridge Breaks Discovery In Integration Mode***[Answer 65887](#)

The ATB asynchronous bridge has no support for integration mode. A static 1 output at the source is transferred as a toggling signal to the sink instead of a static 1.

This issue will not be fixed.

***TPIU Fails To Output Sync After The Pattern Generator Is Disabled In Normal Mode***[Answer 65889](#)

When the TPIU is configured to operate in normal mode (FFCR.EnFCont==0), the synchronization sequence that is required between the test pattern and the trace data is not generated. Synchronization will be generated later as determined by the synchronization counter.

This is a third-party errata (Arm, Inc. 813569); this issue will not be fixed.

***Reset State Of ATB Flush Acknowledge Is Incorrect***[Answer 65890](#)

When any of the following components are held in reset, it will not respond to a flush request: ATB asynchronous bridge, ATB synchronous bridge, ATB funnel, ATB replicator, ATB upsizer, or ATB downsizer.

This is a third-party errata (Arm, Inc. 816720); this issue will not be fixed.

***Timestamp Replicator Might Stall Synchronization***[Answer 65892](#)

Under specific clock ratio conditions, the synchronization operation in the timestamp replicator unit might stall, preventing the timestamp consumers to synchronize with the timestamp replicator unit.

This is a third-party errata (Arm, Inc. 832019); this issue will not be fixed.

**USB 2.0/3.0 Host and Device, and USB 2.0 OTG Controller*****System Might Hang During Suspend/Resume Stages***[Answer 67667](#)

When the USB controller is configured for USB 2.0 and suspend/resume power states are enabled, the controller sends the ULPI PHY a single command to select the termination and transceiver, causing the system to hang when the PHY requires that these be sent in two separate commands.

This issue will not be fixed.

***The tPortConfiguration Timer Resets During Recovery, Violating USB 3.0 Specification***[Answer 68553](#)

When the USB 3.0 link transitions through a recovery state before link management packets (LMPs) are exchanged, the tPortConfiguration timer in the controller resets, causing a violation of the USB 3.0 specification.

This issue will not be fixed.

***USB 2.0 Host Controller Does Not Assert Port Reset In Resume State***[Answer 68554](#)

When the USB 2.0 host controller is in resume state, it does not drive a port reset if register PORTSC.PR is set to 1.

This issue will not be fixed.

***Incorrect Assertion Of Hot Reset Might Occur In USB 3.0 Host Mode***[Answer 68555](#)

When the USB controller is configured in USB 3.0 host mode, the controller might incorrectly enter a recovery state instead of a U1/U2 state when the register PORTSC.PR is set to 1 within a certain timing window, causing a hot reset assertion.

This issue will not be fixed.

### ***Request For U3 Transition Might Get Dropped When The USB 3.0 Host Controller Transitions From U1 To U2 State***

[Answer 68556](#)

In the USB 3.0 host mode, if a U3 transition is requested during a certain timing window of a U1 to U2 state transition, the U3 state transition request might be dropped by the controller.

This issue will not be fixed.

### ***USB Full-Speed Device Does Not Enter Hibernation State During Disconnect***

[Answer 68557](#)

When the controller is configured as a full-speed device and a USB disconnect happens, the controller does not enter the hibernation state if there are pending IN tokens or acknowledgment packets from the host.

This issue will not be fixed.

## **Programmable Logic (PL) Errata Detailed Descriptions**

### **Video Codec Unit**

#### ***Decoding An HEVC Video Bitstream With Level 4 Or 4.1 With Greater Than 4K Pixels Per Line Results In Corruption In The Decoded Picture***

[Answer 69340](#)

Decoding an HEVC encoded stream with level 4 or 4.1 with greater than 4K pixels per line and a coding tree block (CTB) size of 16x16 pixels results in corruption in the decoded picture.

This issue will not be fixed.

#### ***Decoding An HEVC Video Bitstream With 8K Pixels Per Line With Sample Adaptive Offset (SAO) Filter Enabled Results In Corruption In The Decoded Picture***

[Answer 69341](#)

Decoding an HEVC encoded stream with 8K pixels per line and SAO filter enabled results in corruption in the decoded picture.

This issue will not be fixed.

## ***Decoding An 8K CAVLC Video Bitstream Might Hang***

[Answer 69053](#)

If an AVC encoded stream is decoded with CAVLC for an 8K line and there are more than 65,535 consecutive skipped macroblocks in P-frames or B-frames, the decoder might not generate a frame completion interrupt, resulting in a software hang.

This issue will not be fixed.

## **Design Tool Requirements**

Refer to [DS925](#), *Zynq UltraScale+ MPSoC Data Sheet: DC and AC Switching Characteristics* for the minimum Vivado™ software releases required for production. AMD recommends using the latest supported release.

## **Traceability**

Use the device top mark 2D bar code or the electronic device DNA to find device properties via the device lookup tool: <https://xapps9.xilinx.com/2dbarcode/>.

## Revision History

The following table shows the revision history for this document:

Date	Version	Description of Revisions
12/11/2023	1.15	Added XAZU3TEG; updated <a href="#">Table 1</a> .
08/14/2023	1.14	Added XCZU3TCG and XCZU3TEG; updated <a href="#">Table 1</a> .
06/30/2023	1.13	Added <a href="#">Primary Boot Is Not Supported With eMMC Devices That Require CMD6 Busy Time Greater Than 1 ms</a> and <a href="#">CAN Controller Does Not Send A Single Remote Transmission Request</a> . Removed Figure 1.
05/25/2022	1.12	Added XCZU1CG, XCZU1EG, XCZU7EG, and XAZU1EG devices. Added <a href="#">Speculative AT Instruction Using Out-Of-Context Translation Regime Could Cause Subsequent Request To Generate An Incorrect Translation</a> .
02/14/2020	1.11	Replaced Watchpoint On A Load Or Store Multiple Might Be Missed with <a href="#">Watchpoint Access In A Store Multiple Is Not Masked</a> .
09/05/2019	1.10	Added XAZU7EV and XAZU11EG devices and updated IDCODEs for XCZU17EG, XCZU19EG, and XQZU19EQ in <a href="#">Table 1</a> . Updated <a href="#">Traceability</a> section with 2D bar code tool information.
12/07/2018	1.9	Added XQZU3EG, XQZU9EG, and XQZU9EG devices to <a href="#">Table 1</a> . Added <a href="#">DDR Memory Controller Minimum Data Rate Is 1,000Mb/s</a> .
10/30/2018	1.8	Added XQ Zynq UltraScale+ MPSoCs. Updated <a href="#">Figure 1</a> .
08/20/2018	1.7	Added <a href="#">PS DNA Is Not Write Protected And Is Different Than PL DNA</a> .
07/23/2018	1.6	Updated with XAZU4EV and XAZU5EV devices.
04/17/2018	1.5	Added <a href="#">LPDDR3/LPDDR4 Temperature Derating Does Not Work When Initial DRAM Temperature Is Greater Than 85°C</a> .
12/06/2017	1.4	<a href="#">Table 1</a> : Added XCZU4EV, XCZU5EV, and XCZU7EV. Added <a href="#">Programmable Logic (PL) Errata Detailed Descriptions</a> and <a href="#">Table 3</a> for new errata: <a href="#">Decoding An HEVC Video Bitstream With Level 4 Or 4.1 With Greater Than 4K Pixels Per Line Results In Corruption In The Decoded Picture</a> ; <a href="#">Decoding An HEVC Video Bitstream With 8K Pixels Per Line With Sample Adaptive Offset (SAO) Filter Enabled Results In Corruption In The Decoded Picture</a> ; and <a href="#">Decoding An 8K CAVLC Video Bitstream Might Hang</a> .
10/05/2017	1.3	<a href="#">Table 1</a> : Added XCZU11EG, XAZU2EG, and XAZU3EG; updated JTAG ID Code column header to IDCODE[31:0]; and added table note. Added <a href="#">PS DDR Inputs Do Not Switch To Boundary-Scan Compatible Mode</a> .
08/23/2017	1.2	Added XCZU17EG and XCZU19EG to <a href="#">Table 1</a> . Updated <a href="#">Design Tool Requirements</a> .
07/12/2017	1.1	Added <a href="#">Pixel Processor Write Boundary High Address Value Is Constant</a> ; <a href="#">DMA Controller Always Marks Transactions As Secure</a> ; and <a href="#">Multi-lane Link Alignment Of PCIe Might Require Greater Than One SKP Ordered Set</a> .
04/20/2017	1.0	Initial Xilinx release.

## Please Read: Important Legal Notices

The information presented in this document is for informational purposes only and may contain technical inaccuracies, omissions, and typographical errors. The information contained herein is subject to change and may be rendered inaccurate for many reasons, including but not limited to product and roadmap changes, component and motherboard version changes, new model and/or product releases, product differences between differing manufacturers, software changes, BIOS flashes, firmware upgrades, or the like. Any computer system has risks of security vulnerabilities that cannot be completely prevented or mitigated. AMD assumes no obligation to update or otherwise correct or revise this information. However, AMD reserves the right to revise this information and to make changes from time to time to the content hereof without obligation of AMD to notify any person of such revisions or changes. THIS INFORMATION IS PROVIDED "AS IS." AMD MAKES NO REPRESENTATIONS OR WARRANTIES WITH RESPECT TO THE CONTENTS HEREOF AND ASSUMES NO RESPONSIBILITY FOR ANY INACCURACIES, ERRORS, OR OMISSIONS THAT MAY APPEAR IN THIS INFORMATION. AMD SPECIFICALLY DISCLAIMS ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR ANY PARTICULAR PURPOSE. IN NO EVENT WILL AMD BE LIABLE TO ANY PERSON FOR ANY RELIANCE, DIRECT, INDIRECT, SPECIAL, OR OTHER CONSEQUENTIAL DAMAGES ARISING FROM THE USE OF ANY INFORMATION CONTAINED HEREIN, EVEN IF AMD IS EXPRESSLY ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

### **AUTOMOTIVE APPLICATIONS DISCLAIMER**

AUTOMOTIVE PRODUCTS (IDENTIFIED AS "XA" IN THE PART NUMBER) ARE NOT WARRANTED FOR USE IN THE DEPLOYMENT OF AIRBAGS OR FOR USE IN APPLICATIONS THAT AFFECT CONTROL OF A VEHICLE ("SAFETY APPLICATION") UNLESS THERE IS A SAFETY CONCEPT OR REDUNDANCY FEATURE CONSISTENT WITH THE ISO 26262 AUTOMOTIVE SAFETY STANDARD ("SAFETY DESIGN"). CUSTOMER SHALL, PRIOR TO USING OR DISTRIBUTING ANY SYSTEMS THAT INCORPORATE PRODUCTS, THOROUGHLY TEST SUCH SYSTEMS FOR SAFETY PURPOSES. USE OF PRODUCTS IN A SAFETY APPLICATION WITHOUT A SAFETY DESIGN IS FULLY AT THE RISK OF CUSTOMER, SUBJECT ONLY TO APPLICABLE LAWS AND REGULATIONS GOVERNING LIMITATIONS ON PRODUCT LIABILITY.

© Copyright 2017–2023 Advanced Micro Devices, Inc. AMD, the AMD Arrow logo, Zynq, UltraScale+, and combinations thereof are trademarks of Advanced Micro Devices, Inc. AMBA, AMBA Designer, Arm, Arm1176JZ-S, CoreSight, Cortex, and PrimeCell are trademarks of Arm in the EU and other countries. PCI, PCIe and PCI Express are trademarks of PCI-SIG and used under license. Other product names used in this publication are for identification purposes only and may be trademarks of their respective companies.